RIVIERA OAK

Click Engineered Timber





BORA

APOSTLE











"HOME IS WHERE THE HEART IS"

For further information contact Customer Service on 1800 622 293 or visit www.heartridge.com.au

Updated 18-10-18

HEARTRIDGE

The Riviera Oak range of click timber is designed to allow your home to be transformed by the distinctly sophisticated look and feel of an authentic timber floor. This range has been designed to the highest standards of manufacturing and comprises a Valinge 5G click lock, micro-bevelled edges, and a brushed and lacquered surface, making it a floor worthy of the finest home.

Riviera Oak is backed with a lifetime residential structural guarantee and twenty year surface finish guarantee, so that you can be assured that your Heartridge floor will remain beautiful for many years to come, always making your space a place to come home to.

SPECIFICATIONS - GENERAL		
Plank Size	Thickness	14mm
	Veneer	3mm
	Width	190mm
	Length	1900mm
Carton Contents	2.888m ² - 8 Layers	
Nesting	2 Layers maximum. 500mm minimum.	
Weight per Carton	22.0kg	
Pallet	40 cartons - 115.520m²	
Structure	3-Layer: Oak veneer, SPF (Spruce, Pine, Fir) core, Poplar backing	
Veneer	3.0mm European Oak	
Coating	UV-cured lacquer - Klumpp	
Surface Finish	Brushed, matte finish	
Grading	Standard (ABCD)	
Edge	Micro-bevelled (4-sided)	
Joining System	Valinge 5G	
Installation Type	Floated or glued	
Warranty	Structural	Lifetime Residential
	Surface Finish	20 Year Residential

SPECIFICATIONS - TECHNICAL		
Fire - Smoke	34%.min	
Fire - CHF/CRF	3.2 kW/m2	
Slip - Dry Floor Friction	D1	
Slip - Wet Pendulum	P3	
Slip - Oil Wet Ramp	R9	
Formaldehyde	E1	

Colour	Product Code
Bora	825001
Whitehaven	825002
Amalfi	825003
Indus	825004
Apostle	825005
Orinoco	825006
Mandalay	825007
Loire	825008

Timber is a natural material and variations in colour, texture and presence of naturally occurring features are expected. Final product will exhibit variation from sample material. Timber flooring will react to direct sunlight, moisture and humidity in its environment and this must be managed by the homeowner.